

**WARNING!**

AGAINST USING POWER OPERATED TOOLS  
FOR FITTING

**MiniK10 ELECTRONIC CAM LOCKS**

THAT CAN CAUSE DAMAGES THAT WILL VOID THE PRODUCT WARRANTY



USING POWER OPERATED TOOLS TO TIGHTEN THE RETAINER SCREW AT THE TOP OF THE MiniK10 KEYPAD, OR FOR TIGHTENING THE MiniK10 CYLINDER HEX NUT, MAY CAUSE IRREPARABLE DAMAGE TO THE LOCK AND/OR THE INTERNAL ELECTRONIC COMPONENTS.

**FOR THE SAKE OF A FEW SECONDS MORE, WE RECOMMEND USING HAND TOOLS ONLY FOR TIGHTENING FIXINGS**

***FOR ALL DOOR MATERIAL THICKNESSES, YOU MUST USE A SCREW NO LONGER THAN 2mm LONGER THAN THE DOOR THICKNESS. MiniK10 LOCKS ARE SUPPLIED WITH A FACTORY DEFAULT RETAINER SCREW SUITABLE FOR 18mm DOOR THICKNESS. FOR LESS THICKER MATERIAL (16mm) WE RECOMMEND A SMALL WASHER OR A SCREW OF THE APPROPRIATE LENGTH NOT EXCEEDING THE DOOR THICKNESS MORE THAN 2mm***

**WARRANTY WILL NOT BE APPROVED FOR REPAIR OR REPLACEMENT FOR MiniK10 LOCKS DAMAGED BECAUSE OF USING POWER OPERATED TOOLS OR EXCESSIVE OVER-TIGHTENING THAT CAN STRIP THE HEX NUT OR CYLINDER THREADS, BREAKING OF THE CYLINDER AWAY FROM THE MAIN LOCK BODY, EXTRACTING, DISLODGING OR STRIPPING THE RETAINER SCREW BRASS BUSH AT THE TOP OF THE LOCK DUE TO OVER-TIGHTENING OR, FAILURE OF KEYPAD CIRCUIT BOARD OR OTHER ELECTRONIC COMPONENTS WITHIN THE MiniK10 THAT ARE DAMAGED AND EVIDENT OF EXCESSIVE TIGHTENING OR IGNORING MANUFACTURER'S RECOMMENDED INSTALLATION PROCEDURES.**